#### **NIST NCSTAR 1**

Federal Building and Fire Safety Investigation of the World Trade Center Disaster

# Final Report on the Collapse of the World Trade Center Towers



National Institute of Standards and Technology Technology Administration

U.S. Department of Commerce

#### **NIST NCSTAR 1**

Federal Building and Fire Safety Investigation of the World Trade Center Disaster

# Final Report on the Collapse of the World Trade Center Towers

September 2005



U.S. Department of Commerce Carlos M. Gutierrez, Secretary

Technology Administration
Michelle O'Neill, Acting Under Secretary for Technology

National Institute of Standards and Technology William Jeffrey, Director

#### Disclaimer No. 1

Certain commercial entities, equipment, products, or materials are identified in this document in order to describe a procedure or concept adequately or to trace the history of the procedures and practices used. Such identification is not intended to imply recommendation, endorsement, or implication that the entities, products, materials, or equipment are necessarily the best available for the purpose. Nor does such identification imply a finding of fault or negligence by the National Institute of Standards and Technology.

#### Disclaimer No. 2

The policy of NIST is to use the International System of Units (metric units) in all publications. In this document, however, units are presented in metric units or the inch-pound system, whichever is prevalent in the discipline.

#### Disclaimer No. 3

Pursuant to section 7 of the National Construction Safety Team Act, the NIST Director has determined that certain evidence received by NIST in the course of this Investigation is "voluntarily provided safety-related information" that is "not directly related to the building failure being investigated" and that "disclosure of that information would inhibit the voluntary provision of that type of information" (15 USC 7306c).

In addition, a substantial portion of the evidence collected by NIST in the course of the Investigation has been provided to NIST under nondisclosure agreements.

#### Disclaimer No. 4

NIST takes no position as to whether the design or construction of a WTC building was compliant with any code since, due to the destruction of the WTC buildings, NIST could not verify the actual (or as-built) construction, the properties and condition of the materials used, or changes to the original construction made over the life of the buildings. In addition, NIST could not verify the interpretations of codes used by applicable authorities in determining compliance when implementing building codes. Where an Investigation report states whether a system was designed or installed as required by a code *provision*, NIST has documentary or anecdotal evidence indicating whether the requirement was met, or NIST has independently conducted tests or analyses indicating whether the requirement was met.

#### Use in Legal Proceedings

No part of any report resulting from a NIST investigation into a structural failure or from an investigation under the National Construction Safety Team Act may be used in any suit or action for damages arising out of any matter mentioned in such report (15 USC 281a; as amended by P.L. 107-231).

National Institute of Standards and Technology National Construction Safety Team Act Report 1 Natl. Inst. Stand. Technol. Natl. Constr. Sfty. Tm. Act Rpt. 1, 298 pages (September 2005) CODEN: NSPUE2

U.S. GOVERNMENT PRINTING OFFICE WASHINGTON: 2005

## NATIONAL CONSTRUCTION SAFETY TEAM FOR THE FEDERAL **BUILDING AND FIRE SAFETY INVESTIGATION OF THE WORLD TRADE CENTER DISASTER**

S. Shyam Sunder, Sc.D. (NIST) Lead Investigator

Richard G. Gann, Ph.D. (NIST) Final Report Editor; Project Leader, Project 5:

Reconstruction of Thermal and Tenability Environment

William L. Grosshandler, Ph.D. (NIST) Associate Lead Investigator; Project Leader, Project 4:

Investigation of Active Fire Protection Systems

H.S. Lew, Ph.D., P.E. (NIST) Co-Project Leader, Project 1: Analysis of Building and Fire

Codes and Practices

Richard W. Bukowski, P.E. (NIST) Co-Project Leader, Project 1: Analysis of Building and Fire

Codes and Practices

Fahim Sadek, Ph.D. (NIST) Project Leader, Project 2: Baseline Structural Performance

and Aircraft Impact Damage Analysis

Project Leader, Project 3: Mechanical and Metallurgical Frank W. Gayle, Ph.D. (NIST)

Analysis of Structural Steel

John L. Gross, Ph.D., P.E. (NIST) Co-Project Leader, Project 6: Structural Fire Response and

Collapse Analysis

Therese P. McAllister, Ph.D., P.E. (NIST) Co-Project Leader, Project 6: Structural Fire Response and

Collapse Analysis

Jason D. Averill (NIST) Project Leader, Project 7: Occupant Behavior, Egress, and

**Emergency Communications** 

J. Randall Lawson (NIST) Project Leader, Project 8: Fire Service Technologies and

Guidelines

Harold E. Nelson, P.E. Fire Protection Engineering Expert

Stephen A. Cauffman (NIST) Program Manager National Construction Safety Team

This page intentionally left blank.

#### **CONTRIBUTORS TO THE INVESTIGATION**

Jeffrey Fong

#### NIST TECHNICAL STAFF

Mohsen Altafi Robert Anleitner Elisa Baker Stephen Banovic **Howard Baum** Carlos Beauchamp Dale Bentz Charles Bouldin Paul Brand Lori Brassell Kathy Butler Nicholas Carino Sandy Clagett Ishmael Conteh Matthew Covin Frank Davis David Dayan Laurean DeLauter Jonathan Demarest Stuart Dols Michelle Donnelly Dat Duthinh **David Evans** Richard Fields James Filliben

Glenn Forney William Fritz **Anthony Hamins** Edward Hnetkovsky Erik Johnsson Dave Kelley Mark Kile Erica Kuligowski Jack Lee William Luecke Alexander Maranghides David McColskey Chris McCowan Jay McElroy Kevin McGrattan Roy McLane George Mulholland Lakeshia Murray Kathy Notarianni Joshua Novosel Long Phan William Pitts Thomas Ohlemiller Victor Ontiveros Richard Peacock

Lisa Petersen Rochelle Plummer Kuldeep Prasad Natalia Ramirez Ronald Rehm Paul Reneke Michael Riley Lonn Rodine Schuyler Ruitberg Jose Sanchez Raymond Santoyo Steven Sekellick Michael Selepak **Thomas Siewert** Emil Simiu Monica Starnes David Stroup Laura Sugden Robert Vettori John Widmann Brendan Williams Maureen Williams Jiann Yang Robert Zarr

Max Peltz

#### NIST EXPERTS AND CONSULTANTS

Vincent Dunn

Steven Hill

Tim Foecke

John Hodgens

Kevin Malley

Valentine Junker

#### DEPARTMENT OF COMMERCE AND NIST INSTITUTIONAL SUPPORT

Michele Abadia-Dalmau James Hill Karen Perry
Kellie Beall Verna Hines Sharon Rinehart
Arden Bement, Jr. Kathleen Kilmer Michael Rubin

Audra Bingaman Kevin Kimball Rosamond Rutledge-Burns

Sharon Bisco Thomas Klausing John Sanderson
Phyllis Boyd Donna Kline Hratch Semerjian
Marie Bravo Fred Kopatich Sharon Shaffer
Craig Burkhardt Kenneth Lechter Elizabeth Simon
Paul Cataldo Melissa Lieberman Jack Snell

Virginia Covahey Darren Lowe Michael Szwed Deborah Cramer Mark Madsen Kelly Talbott Gail Crum Ronald Meininger Anita Tolliver Jane Dana Romena Moy Joyce Waters Sherri Diaz Michael Newman Teresa Vicente Sandra Febach Gail Porter Dawn Williams

Susan Ford Thomas O'Brian

James Fowler Nualla O'Connor-Kelly

Matthew Heyman Norman Osinski

#### **NIST CONTRACTORS**

#### Applied Research Associates, Inc.

Steven Kirkpatrick\* Marsh Hardy Claudia Navarro
Robert T. Bocchieri Samuel Holmes Brian D. Peterson
Robert W. Cilke Robert A. MacNeill Justin Y-T. Wu

#### Baseline, Inc.

Martin Klain

#### Computer Aided Engineering Associates, Inc.

Peter Barrett\* Daniel Fridline
Michael Bak James J. Kosloski

#### DataSource, Inc.

John Wivaag

#### GeoStats, Inc.

Marcello Oliveira

#### Gilsanz Murray Steficek LLP

Ramon Gilsanz

#### Hughes Associates, Inc.

Ed Budnick\*

Matt Hulcher

John Schoenrock

Mike Ferreira\*

Alwin Kelly

Steven Strege

Mark Hopkins

Chris Mealy

Karen Dawn Tooren

#### **Independent Contractors**

Ajmal Abbasi

David Sharp

Kaspar Willam

Eduardo Kausel

Daniele Veneziano

David Parks

Josef Van Dyck

#### Isolatek International, Inc.

Paulette Kaminski

#### John Jay College

Norman Groner

#### Leslie E. Robertson Associates, R.L.L.P.

William J. Faschan\*

William C. Howell

Richard B. Garlock\*

Raymond C. Lai

#### National Fire Protection Association

Rita Fahey\*

Norma Candeloro

Joseph Molis

#### National Research Council, Canada

Guylene Proulx\*

Amber Walker

#### NuStats, Inc.

Johanna Zmud\*

Christopher Frye

Della Santos

Carlos Arce

Nancy McGuckin

Robert Santos

Heather Contrino

Sandra Rodriguez

Rolf Jensen & Associates, Inc.

Ray Grill\*

Tom Brown

Bob Keough

Ed Armm

Duane Johnson

Joseph Razz

Rosenwasser/Grossman Consulting Engineers, P.C.

Jacob Grossman\* Craig Leech

Arthur Seigel

Science Applications International Corporation

John Eichner\*
Cheri Sawyer\*

Pamela Curry
John DiMarzio

Mark Madara Walter Soverow

Lori Ackman

Heather Duvall

Paul Updike

Marina Bogatine Sydel Cavanaugh

Mark Huffman Charlotte Johnson

Yvonne Zagadou

Kathleen Clark

Michael Kalmar

Simpson Gumpertz & Heger Inc.

Mehdi Zarghamee\*

Ron Hamburger

Wassim I. Naguib

Glenn Bell

Frank Kan Yasuo Kitane

Rasko P. Ojdrovic Andrew T. Sarawit

Said Bolourchi

Ömer O. Erbay

Atis Liepins

Pedro Sifre

Daniel W. Eggers

Michael Mudlock

S. K. Ghosh Associates, Inc.

S. K. Ghosh\*

Dave Fanella

Analdo Derecho

Xumei Liang

Skidmore, Owings & Merrill, LLP

Bill Baker

Bob Sinn

John Zils

Teng & Associates, Inc.

Shankar Nair

Underwriters Laboratories, Inc.

Fred Hervey\*

Mark Izydorek

William Joy

Joseph Treadway\*

Aldo Jimenez

John Mammoser

University at Buffalo, The State University of New York

Andrew Whitaker\*
Andrei Reinhorn
Joshua Repp

University of Chicago Survey

University of Colorado

University of Michigan

<u>Lab</u>

Virginia Bartot Martha van Haitsma Dennis Mileti

Jamie Abelson

Wiss, Janney, Elstner Associates, Inc.

Ray Tide\*
Jim Hauck
Conrad Paulson

**COOPERATING ORGANIZATIONS** 

American Airlines

Desmond Barry Morgan Heyer The Boeing Company

Marlene Nelson

Blanford Land Development

Corporation
Lisa Lickman
Ron Lickman

John Sandy

Carr Futures, Inc.

David Mangold

City of New York Fire

**Department** 

Alexandra Fisher Allen S. Hay Federal Bureau of Investigation

Kenneth Marr

Hugo Neu Schnitzer East

Robert Kelman

Steve Shinn Frank Manzo Laclede Steel

David McGee

Marsh & McLennan

Companies

Thomas Gress Michael Lyons

Metal Management Northeast, Inc.

Michael Henderson Alan Ratner

John Silva

National Commission on Terrorist Attacks Upon the United States

Madeline Blot

Sam M. W. Casperson

George L. Delgrosso

Daniel Marcus

James Miller

Catherine S. Taylor

**New York City Law Department** 

Lawrence S. Kahn

Rachel Relkin

Katherine Winningham

Jay L. Cohen

Joanna Weiss

Jessie Levine

Nancy Seliga

Gary Shaffer

George C. D. Duke

**New York City Police Department** 

Michael F. Healey

The Port Authority of New York and New Jersey

James Begley

Jeffrey Gertier

Saroj Bhol

Frank Lombardi

Gerry Gaeta Alan Reiss

**Siemens** 

Silverstein Properties

Simpson, Thacher & Bartlett

LLP

John Farrington

Robert Salamone

Steven Shamash

Jamie Gamble

Structural Engineers
Association of New York

Wachtell, Lipton, Rosen & Katz

**United Air Lines** 

Ed DiPaolo

Marc Wolinsky

John Midgett

Andrew Cheung

Norvis Huezo

Williams & Connolly LLP

Philip Sechler

<sup>\*</sup>Principal Investigator/Key Contact

#### **DEDICATION**

On the morning of September 11, 2001, Americans and people around the world were shocked by the destruction of the World Trade Center (WTC) in New York City and the devastation of the Pentagon near Washington, D.C., after large aircraft were flown into the buildings, and the crash of an aircraft in a Pennsylvania field that averted further tragedy. Four years later, the world has been changed irrevocably by those terrorist attacks. For some, the absence of people close to them is a constant reminder of the unpredictability of life and death. For millions of others, the continuing threats of further terrorist attacks affect how we go about our daily lives and the attention we must give to homeland security and emergency preparedness.

Within the construction, building, and public safety communities, there arose a question pressing to be answered: How can we reduce our vulnerability to such attacks, and how can we increase our preparedness and safety while still ensuring the functionality of the places in which we work and live?

This Investigation has, to the best extent possible, reconstructed the response of the WTC towers and the people on site to the consequence of the aircraft impacts. It provides improved understanding to the professional communities and building occupants whose action is needed and to those most deeply affected by the events of that morning. In this spirit, this report is dedicated to those lost in the disaster, to those who have borne the burden to date, and to those who will carry it forward to improve the safety of buildings.

Dedication

This page intentionally left blank.

#### ABSTRACT

This is the final report on the National Institute of Standards and Technology (NIST) investigation of the collapse of the World Trade Center (WTC) towers, conducted under the National Construction Safety Team Act. This report describes how the aircraft impacts and subsequent fires led to the collapse of the towers after terrorists flew jet fuel laden commercial airliners into the buildings; whether the fatalities were low or high, including an evaluation of the building evacuation and emergency response procedures; what procedures and practices were used in the design, construction, operation, and maintenance of the towers; and areas in current building and fire codes, standards, and practices that warrant revision. Extensive details are found in the 42 companion reports. The final report on the collapse of WTC 7 will appear in a separate report.

Also in this report is a description of how NIST reached its conclusions. NIST complemented in-house expertise with private sector technical experts; accumulated copious documents, photographs, and videos of the disaster; established baseline performance of the WTC towers; performed computer simulations of the behavior of each tower on September 11, 2001; combined the knowledge gained into a probable collapse sequence for each tower; conducted nearly 1,200 first-person interviews of building occupants and emergency responders; and analyzed the evacuation and emergency response operations in the two high-rise buildings.

The report concludes with a list of 30 recommendations for action in the areas of increased structural integrity, enhanced fire endurance of structures, new methods for fire resistant design of structures, enhanced active fire protection, improved building evacuation, improved emergency response, improved procedures and practices, and education and training.

Keywords: Aircraft impact, building evacuation, emergency response, fire safety, human behavior, structural collapse, tall buildings, wind engineering, World Trade Center.

This page intentionally left blank.

# **TABLE OF CONTENTS**

National Construction Safety Team for the Federal Building and Fire Safety Investigation of the	· · · · · · · · · · · · · · · · · · ·
world Trade Center Disaster	iii
Contributors to the Investigation	v
Dedication	xi
Abstract	xiii
List of Figures	xxi
List of Tables	xxv
List of Acronyms and Abbreviations	xxvii
Preface	xxix
Executive Summary	xxxv
Part I: September 11, 2001	1
Chapter 1 New York City's World Trade Center	
1.1 The Origination	1
1.2 The World Trade Center Complex	1
The World Tidde Conter Complex	2
110 510	2
1.2.2 The Towers	5
Chapter 2	
The Account of World Trade Center 1	19
2.1 8:46:30 a.m. EDT	19
2.2 The Aircraft	20
2.3 The Immediate Damage	20
2.4 The Jet Fuel	24
2.5 8:47 a.m. to 9:02 a.m. EDT	24
2.6 9:02:59 a.m. EDT	27
2.7 9:03 a.m. to 9:57 a.m. EDT	27
2.8 9:58:59 a.m. EDT	32
2.9 9:59 a.m. to 10:28 a.m. EDT	32
2.10 The Outcome	34

Chapte The A	r 3 ccoun	t of World Trade Center 2	37
3.1	8:46:3	0 a.m. EDT	37
3.2	9:02:5	9 a.m. EDT	38
3.3	The In	nmediate Damage	38
3.4	The Je	et Fuel	42
3.5	9:03 a	.m. to 9:36 a.m. EDT	42
3.6	9:36 a	.m. to 9:58 a.m. EDT	44
3.7	The O	Outcome	45
Chapte The T	r 4 oll		47
Part II	: Reco	onstructing the Disaster	49
Chapte The D	r 5 esign	and Construction of the Towers	51
5.1	Build	ing and Fire Codes	51
5.2	The C	Codes and the Towers	52
	5.2.1	The New York City Building Code	52
	5.2.2	Pertinent Construction Provisions	53
	5.2.3	Tenant Alteration Process	54
5.3	Build	ing Design	55
		Loads	
		Aircraft Impact	
		Construction Classification and Fire Resistance Rating	
	5.3.4	Compartmentation	56
	5.3.5	Egress Provisions	57
	5.3.6	Active Fire Protection	61
5.4	Build	ing Innovations	64
	5.4.1	The Need for Innovations	64
	5.4.2	Framed Tube System	64
	5.4.3	Deep Spandrel Plates	
	5.4.4	Uniform External Column Geometry	65
	5.4.5	Wind Tunnel Test Data to Establish Wind Loads	65
	516	Viscoelastic Dampers	65

	5.4.7	Long-Span Composite Floor Assemblies
	5.4.8	Vertical Shaft Wall Panels66
5.5	Struct	tural Steels67
	5.5.1	Types and Sources
	5.5.2	Properties67
5.6	Fire P	rotection of Structural Steel
	5.6.1	Thermal Insulation
	5.6.2	Use of Insulation in the WTC Towers
5.7	Conc	rete
5.8	The T	enant Spaces
	5.8.1	General
	5.8.2	Walls
	5.8.3	Flooring
	5.8.4	Ceilings
	5.8.5	Furnishings
	nstruct	tion of the Collapses81
6.1	Appro	ach
6.2	Devel	opment of the Disaster Timeline
6.3	Learni	ing from the Visual Images
6.4		ing from the Recovered Steel
	6.4.1	Collection of Recovered Steel
		Mechanical and Physical Properties
	6.4.3	Damage Analysis89
6.5	Inform	nation Gained from Other WTC Fires
6.6	The B	uilding Structural Models92
	6.6.1	Computer Simulation Software92
	6.6.2	The Reference Models92
	6.6.3	Building Structural Models for Aircraft Impact Analysis
	6.6.4	Building Structural Models for Structural Response to Impact Damage and Fire and Collapse Initiation Analysis
6.7	The A	ircraft Structural Model
6.8	Aircra	ft Impact Modeling107
	6.8.1	Component Level Analyses
	6.8.2	Subassembly Impact Analyses

#### Table of Contents

	6.8.3	Aircraft Impact Conditions	108
	6.8.4	Global Impact Analysis	109
6.9	Aircra	ft Impact Damage Estimates	112
	6.9.1	Structural and Contents Damage	112
	6.9.2	Validity of Impact Simulations	116
	6.9.3	Damage to Thermal Insulation	
	6.9.4	Damage to Ceiling System	120
	6.9.5	Damage to Interior Walls and Furnishings	120
6.16	) Therm	al Environment Modeling	121
	6.10.1	Need for Simulation	121
	6.10.2	Modeling Approach	121
	6.10.3	The Four Cases	126
	6.10.4	Characterization of the Fires	127
	6.10.5	Global Heat Release Rates	130
6.11	Data T	ransfer	131
6.12	2 Therm	al Mapping	131
	6.12.1	Approach	131
	6.12.2	The Fire-Structure Interface	131
	6.12.3	Thermal Insulation Properties	132
	6.12.4	FSI Uncertainty Assessment	133
	6.12.5	The Four Cases	138
	6.12.6	Characterization of the Thermal Profiles	141
6.13	Measu	rement of the Fire Resistance of the Floor System	141
6.14	Collap	se Analysis of the Towers	143
	6.14.1	Approach to Determining the Probable Collapse Sequences	143
	6.14.2	Results of Global Analysis of WTC 1	144
	6.14.3	Results of Global Analysis of WTC 2	145
	6.14.4	Events Following Collapse Initiation	146
	6.14.5	Structural Response of the WTC Towers to Fire without Impact or Thermal Insulation Damage	146
	6.14.6	Probable WTC 1 Collapse Sequence	
	6.14.7	Probable WTC 2 Collapse Sequence	. 151
	6.14.8	Accuracy of the Probable Collapse Sequences	152
		Factors that Affected Building Performance on September 11, 2001	

Chapte Recor	r 7 I <b>stru</b> ct	ion of Human Activity	155
		ng Occupants	
	7.1.1	Background	155
	7.1.2	The Building Egress System	155
	7.1.3	The Evacuation—Data Sources	157
	7.1.4	Occupant Demographics	158
	7.1.5	Evacuation of WTC 1	158
	7.1.6	Evacuation of WTC 2	160
7.2	Emerg	gency Responders	163
	7.2.1	Data Gathered	163
	7.2.2	Operation Changes following the WTC 1 Bombing on February 26, 1993	164
	7.2.3	Responder Organization	166
	7.2.4	Responder Access	169
	7.2.5	Communications	170
	7.2.6	The Overall Response	172
7.3	Factor	rs That Contributed to Enhanced Life Safety	172
	7.3.1	Aggregate Factors	172
	7.3.2	Individual Factors	172
		Outcome of the investigation	173
Chapte Princi	r 8  pal Fi	ndings	175
8.1	Introd	uction	175
8.2	Sumn	nary	175
8.3	Findi	ngs on the Mechanisms of Building Collapse	179
	8.3.1	Summary of Probable Collapse Sequences	179
	8.3.2	Structural Steels	180
	8.3.3	Aircraft Impact Damage Analysis	182
	8.3.4	Reconstruction of the Fires	183
	8.3.5	Structural Response and Collapse Analysis	185
8.4	Findi	ngs on Factors Affecting Life Safety	186
	8.4.1	Active Fire Protection	186
	8.4.2	Evacuation	
	8.4.3	Emergency Response	191

#### Table of Contents

8.5	Findir	gs on Operational Codes, Standards, and Practices	194
	8.5.1	General	
	8.5.2	Structural Safety	195
	8.5.3	Fire Safety	
8.6	Future	Factors That Could Have Improved Life Safety	199
	8.6.1	Building Performance Factors	
	8.6.2	Human Performance Factors	
Chapte Recor	r 9 nmend	dations	201
9.1	Build	ng Regulations	201
9.2	NIST Emer	's Recommendations for Improving the Safety of Buildings, Occupants, and gency Responders	202
	9.2.1	Group 1. Increased Structural Integrity	205
		Group 2. Enhanced Fire Endurance of Structures	
	9.2.3	Group 3. New Methods for Fire Resistant Design of Structures	21
	9.2.4	Group 4. Improved Active Fire Protection	213
	9.2.5	Group 5. Improved Building Evacuation	
	9.2.6	Group 6. Improved Emergency Response	218
	9.2.7	Group 7. Improved Procedures and Practices	220
	9.2.8	Group 8. Education and Training	
0.2	Moset	Ctana	223

Appendix A National Construction Safety Team Act

Appendix B
World Trade Center Investigation Publications

Appendix C Subject Index of Supporting Investigation Reports

# **LIST OF FIGURES**

Figure P-1.	The eight projects in the federal building and fire safety investigation of the WTC disaster.	xxxi
Figure 1–1.	The World Trade Center in Lower Manhattan	3
Figure 1-2.	Lower Manhattan and the World Trade Center towers	
Figure 1-3.	Tower floor plans with column numbers.	
Figure 1-4.	Perimeter column/spandrel assembly and floor structure.	
Figure 1–5.	Plan of the 96 <sup>th</sup> floor of WTC 1 showing the core and tenant spaces	
Figure 1-6.	Schematic of composite floor truss system	
Figure 1–7.	Schematic of a hat truss.	
Figure 1-8.	Photograph of insulated WTC trusses	
Figure 1–9.	Schematic of the three-tier elevator system.	
Figure 1–10.		
Figure 1-11.	Views of typical WTC office floors	
	A WTC trading floor	
		•
Figure 2–1.	Simulated impact of American Airlines Flight 11 with WTC 1.	19
Figure 2–2.	Aircraft entry hole on the north side of WTC 1, photographed 30 s after impact	
Figure 2–3.	South face damage of WTC 1 with key aircraft component locations marked	
Figure 2–4.	Simulation of cumulative aircraft impact damage to floors 93 through 98 in WTC 1	
Figure 2–5.	Representation of exterior views of the fires on the four faces of WTC 1 from 8:47 a.m. to about 9:02 a.m.	
Figure 2-6.	Firefighters on the scene at about 9:07 a.m.	
Figure 2–7.	Representation of exterior views of the fires on the four faces of WTC 1 from about 9:38 a.m. to 9:58 a.m.	
Figure 2–8.	Steel surface temperatures on the bottom chords of fire-exposed trusses, uninsulated and insulated with ¾ in. of BLAZE-SHIELD DC/F	
Figure 2–9.	Temperature dependence of yield strength of structural steel as a fraction of the value at room temperature.	
Figure 2-10.	Simulated temperatures of two adjacent trusses (left) and two adjacent perimeter columns (right) exposed to the fires in WTC 1	
Figure 2–11.	Temperature contours (°C) on the top and bottom faces of the concrete slab (96 <sup>th</sup> floor, WTC 1) at 100 min after impact. A portion of the concrete slab on the north face (top) was damaged by the impact of the aircraft.	

Figure 2–12.	2. South face of WTC 1 at 10:23 a.m., showing inward buckling (in inches) of perimeter columns	
Figure 3–1.	Imminent impact of United Airlines Flight 175 with WTC 2	38
Figure 3–2.	South face damage of WTC 2 with key aircraft component locations marked	39
Figure 3–3.	Simulation of aircraft impact damage to the 78th through 83rd floors in WTC 2	40
Figure 3–4.	Representation of exterior views of the fires on the four faces of WTC 2 at about 9:20 a.m.	43
Figure 3–5.	Photograph of WTC 2 tilting to the southeast at the onset of collapse	
Figure 4–1.	The WTC site on September 17, 2001.	47
Figure 5–1.	Fire Command Desk in WTC 1, as seen from a mezzanine elevator, looking west	61
Figure 5–2.	Schematic of sprinkler and standpipe systems.	63
Figure 5–3.	Diagram of floor truss showing viscoelastic damper	66
Figure 5–4.	Ratio of measured yield strength (F <sub>y</sub> ) to specified minimum yield strength for steels used in WTC perimeter columns.	69
Figure 5–5.	Irregularity of coating thickness and gaps in coverage on SFRM-coated bridging trusses	71
Figure 5–6.	Thermal insulation for perimeter columns.	
Figure 5–7.	Temperature-dependent concrete properties.	75
Figure 5–8.	A WTC workstation	76
Figure 6–1.	9:26:20 a.m. showing the east face of WTC 2.	85
Figure 6–2.	Close-up of section of Figure 6–1	86
Figure 6–3.	Examples of a WTC 1 core column (left) and truss material (right)	88
Figure 6-4.	WTC 1 exterior panel hit by the fuselage of the aircraft	88
Figure 6–5.	WTC 1 exterior panel hit by the nose of the aircraft	
Figure 6–6.	Structural model of the 96 <sup>th</sup> floor of WTC 1	
Figure 6–7.	Model of the 96 <sup>th</sup> floor of WTC 1, including interior contents and partitions	95
Figure 6–8.	Multi-floor global model of WTC 1, viewed from the north	96
Figure 6-9.	Multi-floor global model of WTC 2, viewed from the south	96
	Finite element model of an exterior truss seat.	
Figure 6 11	Vertical displacement at 700 °C	
rigule 0-11.	vertical displacement at 700 C	90
Figure 6–11.	ANSYS model of 96 <sup>th</sup> floor of WTC 1.	98

Figure 6-14	Pratt & Whitney PW4000 turbofan engine model
Figure 6-15	Boeing 767-200ER showing the jet fuel distribution at time of impact
Figure 6–16	Calculated impact on an exterior wall by a fuel-laden wing section 107
Figure 6–17.	Response of a tower subassembly model to engine impact
Figure 6-18.	Side view of simulated aircraft impact into WTC 1, Case B
Figure 6-19.	Column damage levels
Figure 6-20.	Case B damage to the slab of floor 96 of WTC 1
Figure 6–21.	Case B simulation of response of contents of 96 <sup>th</sup> floor of WTC 1113
Figure 6-22.	Combined structural damage to the floors and columns of WTC 1, Case A 114
Figure 6-23.	Combined structural damage to the floors and columns of WTC 1, Case B 114
	Combined structural damage to the floors and columns of WTC 2, Case C 115
	Combined structural damage to the floors and columns of WTC 2, Case D 115
	Observed and Case A calculated damage to the north face of WTC 1 117
Figure 6–27.	Schematic of observed damage (top) and Case A calculated damage (lower) to the north face of WTC 1
Figure 6–28.	Schematic of observed damage (above) and Case C calculated damage (right) to the south face of WTC 2
Figure 6-29.	Ceiling tile system mounted on the shaking table
Figure 6-30.	Eight floor model of WTC 1 prior to aircraft impact
Figure 6–31.	Fire test of a single workstation
Figure 6–32.	Interior view of a three-workstation fire test
Figure 6-33.	Rubblized workstations
Figure 6–34.	Three-workstation fire test, 2 min after the start
	Measured and predicted heat release rate from the burning of three office workstations
Figure 6–36.	Upper layer temperatures on the 94 <sup>th</sup> floor of WTC 1, 15 min after impact 127
	Direction of simulated fire movement on floors 94 and 97 of WTC 1 128
Figure 6–38.	Predicted heat release rates for fires in WTC 1 and WTC 2
Figure 6–39.	Simple bar dimensions (in.).
Figure 6–40.	Tubular column dimensions (in.)
Figure 6-41.	Truss Dimensions (in.)
	SFRM-coated steel components prior to a test
Figure 6–43.	Finite element representation of the insulated steel truss (blue), the SFRM (violet), and the ceiling (red)
Figure 6–44.	Comparison of numerical simulations with measurements for the steel surface temperature at four locations on the top chord of a hare trues.

Figure 7–3.

Figure 7–4.

Figure 7-5.

Figure 7-6.

Figure 7–7.

Figure 6–45.	Comparison of numerical simulations with measurements for the temperature of the steel surface at four locations on the top chord of an insulated truss.	. 137
Figure 6–46.	Temperatures (°C) on the columns and trusses of the 96 <sup>th</sup> floor of WTC 1 at 6,000 s after aircraft impact, Case B.	. 139
Figure 6–47.	Temperatures (°C) on the columns and trusses of the 81 <sup>st</sup> floor of WTC 2 at 3,000 s after aircraft impact, Case D.	. 139
Figure 6–48.	Frames from animation of the thermal response of columns on the 96 <sup>th</sup> floor of WTC 1, Case A	. 140
Figure 7–1.	Simulated impact damage to 95 <sup>th</sup> floor of WTC 1, including stairwells, 0.7 s after impact	. 156
Figure 7–2.	Simulated impact damage to WTC 2 on floor 78, 0.62 s after impact	

Observations of building damage after initial awareness but before beginning

Fire Command Board located in the lobby of WTC 1......168

# **LIST OF TABLES**

Table P-1.	Federal building and fire safety investigation of the WTC disaster	XXX
Table P-2.	Public meetings and briefings of the WTC Investigationxxx	
Table E-1.	Topics of NIST recommendations for improved public safety in tall and high-risk buildings.	xliv
Table 1–1.	Use of floors in the WTC towers.	5
Table 2–1.	Locations of occupants of WTC 1.	26
Table 3–1.	Tenants on impact floors in WTC 2	39
Table 3–2.	Location of occupants of WTC 2	42
Table 4–1.	Likely locations of WTC decedents at time of impact	
Table 5–1.	Specified steel grades for various applications.	67
Table 5–2.	Types and locations of SFRM on fire floors.	74
Table 5–3.	Floors of focus	
Table 6–1.	Times for major events on September 11,2001	84
Table 6–2.	Indications of major structural changes up to collapse initiation	87
Table 6-3.	Measured and calculated natural vibration periods (s) for WTC 1	93
Table 6–4.	Summary of aircraft impact conditions	108
Table 6–5.	Input parameters for global impact analyses	109
Table 6–6.	Values of WTC fire simulation variables	126
Table 6–7.	Summary of insulation on steel components.	136
Table 6–8.	Regions in WTC 1 in which temperatures of structural steel exceeded 600 °C	141
Table 6–9.	Regions in WTC 2 in which temperatures of structural steel exceeded 600 °C	. 141
Table 6–10.	Comparison of global structural model predictions and observations for WTC 1, Case B.	153
Table 6–11.	Comparison of global structural model predictions and observations for WTC 2, Case D.	. 153

List of Tables

This page intentionally left blank.

### LIST OF ACRONYMS AND ABBREVIATIONS

#### **Acronyms**

AA American Airlines

ARA Application Research Associates

**ASTM** ASTM International

**BOCA Building Officials and Code Administrators** 

BPS **Building Performance Study** 

**FCD** Fire Command Desk

**FDNY** The Fire Department of the City of New York

**FDS** Fire Dynamics Simulator

Federal Emergency Management Agency **FEMA** 

FSI Fire Structure Interface

**IBC** International Building Code

LERA Leslie E. Robertson Associates

**NFPA** National Fire Protection Association

NIST National Institute of Standards and Technology

NYC New York City

NYPD New York City Police Department

NYS New York State

**PANYNJ** The Port Authority of New York and New Jersey

**PAPD** Port Authority Police Department

**SFRM** sprayed fire-resistive material

**SGH** Simpson Gumpertz & Heger, Inc.

SOM Skidmore, Owings and Merrill

UA United Airlines

USC United States Code

WSHJ Worthington, Skilling, Helle and Jackson

WTC World Trade Center

WTC 1 World Trade Center 1 (North Tower)

# PREFACE

#### Genesis of This Investigation

Immediately following the terrorist attack on the World Trade Center (WTC) on September 11, 2001, the Federal Emergency Management Agency (FEMA) and the American Society of Civil Engineers began planning a building performance study of the disaster. The week of October 7, as soon as the rescue and search efforts ceased, the Building Performance Study Team went to the site and began its assessment. This was to be a brief effort, as the study team consisted of experts who largely volunteered their time away from their other professional commitments. The Building Performance Study Team issued its report in May 2002, fulfilling its goal "to determine probable failure mechanisms and to identify areas of future investigation that could lead to practical measures for improving the damage resistance of buildings against such unforeseen events."

On August 21, 2002, with funding from the U.S. Congress through FEMA, the National Institute of Standards and Technology (NIST) announced its building and fire safety investigation of the WTC disaster. On October 1, 2002, the National Construction Safety Team Act (Public Law 107-231), was signed into law. (A copy of the Public Law is included in Appendix A). The NIST WTC Investigation was conducted under the authority of the National Construction Safety Team Act.

The goals of the investigation of the WTC disaster were:

- To investigate the building construction, the materials used, and the technical conditions that contributed to the outcome of the WTC disaster.
- To serve as the basis for:
  - Improvements in the way buildings are designed, constructed, maintained, and used;
  - Improved tools and guidance for industry and safety officials;
  - Recommended revisions to current codes, standards, and practices; and
  - Improved public safety.

#### The specific objectives were:

- 1. Determine why and how WTC 1 and WTC 2 collapsed following the initial impacts of the aircraft and why and how WTC 7 collapsed;
- 2. Determine why the injuries and fatalities were so high or low depending on location, including all technical aspects of fire protection, occupant behavior, evacuation, and emergency response;
- 3. Determine what procedures and practices were used in the design, construction, operation, and maintenance of WTC 1, 2, and 7; and
- 4. Identify, as specifically as possible, areas in current building and fire codes, standards, and practices that warrant revision.

Page 30 of 48

#### List of Acronyms and Abbreviations

World Trade Center 2 (South Tower) WTC 2

WTC 7 World Trade Center 7

#### **Abbreviations and Conversion Factors**

 $T (^{\circ}C) = 5/9 [T (^{\circ}F) - 32]$ degrees Celsius °C

degrees Fahrenheit ٥F

feet ft

 $1 \text{ gal} = 3.78 \times 10^{-3} \text{ m}^3$ gallon gal

GJ gigajoule

GW gigawatt

inch in.

kilogram kg

kip 1,000 lb/in.2 ksi

1,000 lb

1 lb = 0.453 kgpound lb

1 m = 3.28 ftm meter

micrometer μm

minute min

megajoule MJ megawatt MW

pounds per square inch psi

second S

T temperature NIST is a nonregulatory agency of the U.S. Department of Commerce's Technology Administration. The purpose of NIST investigations is to improve the safety and structural integrity of buildings in the United States, and the focus is on fact finding. NIST investigative teams are authorized to assess building performance and emergency response and evacuation procedures in the wake of any building failure that has resulted in substantial loss of life or that posed significant potential of substantial loss of life. NIST does not have the statutory authority to make findings of fault nor negligence by individuals or organizations. Further, no part of any report resulting from a NIST investigation into a building failure or from an investigation under the National Construction Safety Team Act may be used in any suit or action for damages arising out of any matter mentioned in such report (15 USC 281a, as amended by Public Law 107-231).

#### Organization of the Investigation

The National Construction Safety Team for this Investigation, appointed by the then NIST Director, Dr. Arden L. Bement, Jr., was led by Dr. S. Shyam Sunder. Dr. William L. Grosshandler served as Associate Lead Investigator, Mr. Stephen A. Cauffman served as Program Manager for Administration, and Mr. Harold E. Nelson served on the team as a private sector expert. The Investigation included eight interdependent projects whose leaders comprised the remainder of the team. A detailed description of each of these eight projects is available at http://wtc.nist.gov. The purpose of each project is summarized in Table P-1, and the key interdependencies among the projects are illustrated in Fig. P-1.

Table P-1. Federal building and fire safety investigation of the WTC disaster.

Table F-1. Federal building and fire safety investigation of the WTC disaster.			
Technical Area and Project Leader	Project Purpose		
Analysis of Building and Fire Codes and Practices; Project Leaders: Dr. H. S. Lew and Mr. Richard W. Bukowski	Document and analyze the code provisions, procedures, and practices used in the design, construction, operation, and maintenance of the structural, passive fire protection, and emergency access and evacuation systems of WTC 1, 2, and 7.		
Baseline Structural Performance and Aircraft Impact Damage Analysis; Project Leader: Dr. Fahim H. Sadek	Analyze the baseline performance of WTC 1 and WTC 2 under design, service, and abnormal loads, and aircraft impact damage on the structural, fire protection, and egress systems.		
Mechanical and Metallurgical Analysis of Structural Steel; Project Leader: Dr. Frank W. Gayle	Determine and analyze the mechanical and metallurgical properties and quality of steel, weldments, and connections from steel recovered from WTC 1, 2, and 7.		
Investigation of Active Fire Protection Systems; Project Leader: Dr. David D. Evans; Dr. William Grosshandler	Investigate the performance of the active fire protection systems in WTC 1, 2, and 7 and their role in fire control, emergency response, and fate of occupants and responders.		
Reconstruction of Thermal and Tenability Environment; Project Leader: Dr. Richard G. Gann	Reconstruct the time-evolving temperature, thermal environment, and smoke movement in WTC 1, 2, and 7 for use in evaluating the structural performance of the buildings and behavior and fate of occupants and responders.		
Structural Fire Response and Collapse Analysis; Project Leaders: Dr. John L. Gross and Dr. Therese P. McAllister	Analyze the response of the WTC towers to fires with and without aircraft damage, the response of WTC 7 in fires, the performance of composite steel-trussed floor systems, and determine the most probable structural collapse sequence for WTC 1, 2, and 7.		
Occupant Behavior, Egress, and Emergency Communications; Project Leader: Mr. Jason D. Averill	Analyze the behavior and fate of occupants and responders, both those who survived and those who did not, and the performance of the evacuation system.		
Emergency Response Technologies and Guidelines; Project Leader: Mr. J. Randall Lawson	Document the activities of the emergency responders from the time of the terrorist attacks on WTC 1 and WTC 2 until the collapse of WTC 7, including practices followed and technologies used.		




Figure P-1. The eight projects in the federal building and fire safety investigation of the WTC disaster.

#### **National Construction Safety Team Advisory Committee**

The NIST Director also established an advisory committee as mandated under the National Construction Safety Team Act. The initial members of the committee were appointed following a public solicitation. These were:

- Paul Fitzgerald, Executive Vice President (retired) FM Global, National Construction Safety
   Team Advisory Committee Chair
- John Barsom, President, Barsom Consulting, Ltd.
- John Bryan, Professor Emeritus, University of Maryland
- David Collins, President, The Preview Group, Inc.
- Glenn Corbett, Professor, John Jay College of Criminal Justice
- Philip DiNenno, President, Hughes Associates, Inc.

Robert Hanson, Professor Emeritus, University of Michigan

Document 25-3

- Charles Thornton, Co-Chairman and Managing Principal, The Thornton-Tomasetti Group, Inc.
- Kathleen Tierney, Director, Natural Hazards Research and Applications Information Center, University of Colorado at Boulder
- Forman Williams, Director, Center for Energy Research, University of California at San

This National Construction Safety Team Advisory Committee provided technical advice during the Investigation and commentary on drafts of the Investigation reports prior to their public release. NIST has benefited from the work of many people in the preparation of these reports, including the National Construction Safety Team Advisory Committee. The content of the reports and recommendations, however, are solely the responsibility of NIST.

#### **Public Outreach**

During the course of this Investigation, NIST held public briefings and meetings (listed in Table P-2) to solicit input from the public, present preliminary findings, and obtain comments on the direction and progress of the Investigation from the public and the Advisory Committee.

NIST maintained a publicly accessible Web site during this Investigation at http://wtc.nist.gov. The site contained extensive information on the background and progress of the Investigation.

#### NIST's WTC Public-Private Response Plan

The collapse of the WTC buildings has led to broad reexamination of how tall buildings are designed, constructed, maintained, and used, especially with regard to major events such as fires, natural disasters, and terrorist attacks. Reflecting the enhanced interest in effecting necessary change, NIST, with support from Congress and the Administration, has put in place a program, the goal of which is to develop and implement the standards, technology, and practices needed for cost-effective improvements to the safety and security of buildings and building occupants, including evacuation, emergency response procedures, and threat mitigation.

The strategy to meet this goal is a three-part, NIST-led, public-private response program that includes:

- A federal building and fire safety investigation to study the most probable factors that contributed to post-aircraft impact collapse of the WTC towers and the 47-story WTC 7 building, and the associated evacuation and emergency response experience.
- A research and development (R&D) program to (a) facilitate the implementation of recommendations resulting from the WTC Investigation, and (b) provide the technical basis for cost-effective improvements to national building and fire codes, standards, and practices that enhance the safety of buildings, their occupants, and emergency responders.

Table P-2. Public meetings and briefings of the WTC Investigation.

Date	Location	Principal Agenda
June 24, 2002	New York City, NY	Public meeting: Public comments on the <i>Draft Plan</i> for the pending WTC Investigation.
August 21, 2002	Gaithersburg, MD	Media briefing announcing the formal start of the Investigation.
December 9, 2002	Washington, DC	Media briefing on release of the <i>Public Update</i> and NIST request for photographs and videos.
April 8, 2003	New York City, NY	Joint public forum with Columbia University on first-person interviews.
April 29–30, 2003	Gaithersburg, MD	NCST Advisory Committee meeting on plan for and progress on WTC Investigation with a public comment session.
May 7, 2003	New York City, NY	Media briefing on release of May 2003 Progress Report.
August 26–27, 2003	Gaithersburg, MD	NCST Advisory Committee meeting on status of the WTC investigation with a public comment session.
September 17, 2003	New York City, NY	Media and public briefing on initiation of first-person data collection projects.
December 2–3, 2003	Gaithersburg, MD	NCST Advisory Committee meeting on status and initial results and release of the <i>Public Update</i> with a public comment session.
February 12, 2004	New York City, NY	Public meeting on progress and preliminary findings with public comments on issues to be considered in formulating final recommendations.
June 18, 2004	New York City, NY	Media/public briefing on release of June 2004 Progress Report.
June 22–23, 2004	Gaithersburg, MD	NCST Advisory Committee meeting on the status of and preliminary findings from the WTC Investigation with a public comment session.
August 24, 2004	Northbrook, IL	Public viewing of standard fire resistance test of WTC floor system at Underwriters Laboratories, Inc.
October 19–20, 2004	Gaithersburg, MD	NCST Advisory Committee meeting on status and near complete set of preliminary findings with a public comment session.
November 22, 2004	Gaithersburg, MD	NCST Advisory Committee discussion on draft annual report to Congress, a public comment session, and a closed session to discuss pre-draft recommendations for WTC Investigation.
April 5, 2005	New York City, NY	Media and public briefing on release of the probable collapse sequence for the WTC towers and draft reports for the projects on codes and practices, evacuation, and emergency response.
June 23, 2005	New York City, NY	Media and public briefing on release of all draft reports for the WTC towers and draft recommendations for public comment.
September 12–13, 2005	Gaithersburg, MD	NCST Advisory Committee meeting on disposition of public comments and update to draft reports for the WTC towers.
September 13–15, 2005	Gaithersburg, MD	WTC Technical Conference for stakeholders and technical community for dissemination of findings and recommendations and opportunity for the public to make technical comments.

A dissemination and technical assistance program (DTAP) to (a) engage leaders of the
construction and building community in ensuring timely adoption and widespread use of
proposed changes to practices, standards, and codes resulting from the WTC Investigation
and the R&D program, and (b) provide practical guidance and tools to better prepare facility
owners, contractors, architects, engineers, emergency responders, and regulatory authorities
to respond to future disasters.

The desired outcomes are to make buildings, occupants, and first responders safer in future disaster events.

#### National Construction Safety Team Reports on the WTC Investigation

This report covers the WTC towers, with a separate report on the 47-story WTC 7. Supporting documentation of the techniques and technologies used in the reconstruction are in a set of companion reports that provide more detailed documentation of the Investigation findings and the means by which these technical results were achieved. As such, they are part of the archival record of this Investigation. The titles of the full set of Investigation publications are listed in Appendix B.

## **EXECUTIVE SUMMARY**

## **E.1 GENESIS OF THIS INVESTIGATION**

On August 21, 2002, the National Institute of Standards and Technology (NIST) announced its building and fire safety investigation of the World Trade Center (WTC) disaster. This WTC Investigation was then conducted under the authority of the National Construction Safety Team (NCST) Act, which was signed into law on October 1, 2002. A copy of the Public Law is included in Appendix A.

The goals of the investigation of the WTC disaster were:

- To investigate the building construction, the materials used, and the technical conditions that contributed to the outcome of the WTC disaster after terrorists flew large jet-fuel laden commercial airliners into the WTC towers.
- To serve as the basis for:
  - Improvements in the way buildings are designed, constructed, maintained, and used;
  - Improved tools and guidance for industry and safety officials;
  - Recommended revisions to current codes, standards, and practices; and
  - Improved public safety

### The specific objectives were:

- 1. Determine why and how WTC 1 and WTC 2 collapsed following the initial impacts of the aircraft and why and how WTC 7 collapsed;
- 2. Determine why the injuries and fatalities were so high or low depending on location, including all technical aspects of fire protection, occupant behavior, evacuation, and emergency response;
- 3. Determine what procedures and practices were used in the design, construction, operation, and maintenance of WTC 1, 2, and 7; and

Page 37 of 48

NIST is a nonregulatory agency of the U.S. Department of Commerce. The purpose of NIST investigations is to improve the safety and structural integrity of buildings in the United States, and the focus is on fact finding. NIST investigative teams are authorized to assess building performance and emergency response and evacuation procedures in the wake of any building failure that has resulted in substantial loss of life or that posed significant potential of substantial loss of life. NIST does not have the statutory authority to make findings of fault nor negligence by individuals or organizations. Further, no part of any report resulting from a NIST investigation into a building failure or from an investigation under the National Construction Safety Team Act may be used in any suit or action for damages arising out of any matter mentioned in such report (15 USC 281a, as amended by P.L. 107-231).

4. Identify, as specifically as possible, areas in current building and fire codes, standards, and practices that warrant revision.

#### **E.2 APPROACH**

To meet these goals, NIST complemented its in-house expertise with an array of specialists in key technical areas. In all, over 200 staff contributed to the Investigation. NIST and its contractors compiled and reviewed tens of thousand of pages of documents; conducted interviews with over a thousand people who had been on the scene or who had been involved with the design, construction, and maintenance of the WTC; analyzed 236 pieces of steel that were obtained from the wreckage; performed laboratory tests, measured material properties, and performed computer simulations of the sequence of events that happened from the instant of aircraft impact to the initiation of collapse for each tower.

Cooperation in obtaining the resource materials and in interpreting the results came from a large number of individuals and organizations, including The Port Authority of New York and New Jersey and its contractors and consultants; Silverstein Properties and its contractors and consultants; the City of New York and its departments; the manufacturers and fabricators of the building components; the companies that insured the WTC towers; the building tenants; the aircraft manufacturers; the airlines; the public, including survivors and family members; and the media.

The scarcity of physical evidence that is typically available in place for reconstruction of a disaster led to the following approach:

- Accumulation of copious photographic and video material. With the assistance of the media, public agencies and individual photographers, NIST acquired and organized nearly 7,000 segments of video footage, totaling in excess of 150 hours and nearly 7,000 photographs representing at least 185 photographers. This guided the Investigation Team's efforts to determine the condition of the buildings following the aircraft impact, the evolution of the fires, and the subsequent deterioration of the structure.
- Establishment of the baseline performance of the WTC towers, i.e., estimating the expected performance of the towers under normal design loads and conditions. The baseline performance analysis also helped to estimate the ability of the towers to withstand the unexpected events of September 11, 2001. Establishing the baseline performance of the towers began with the compilation and analysis of the procedures and practices used in the design, construction, operation, and maintenance of the structural, fire protection, and egress systems of the WTC towers. The additional components of the performance analysis were the standard fire resistance of the WTC truss-framed floor system, the quality and properties of the structural steels used in the towers, and the response of the WTC towers to the design gravity and wind loads.
- Simulations of the behavior of each tower on September 11, 2001, in four steps:
  - 1. The aircraft impact into the tower, the resulting distribution of aviation fuel, and the damage to the structure, partitions, thermal insulation materials, and building contents.
  - 2. The evolution of multi-floor fires.

- 3. The heating and consequent weakening of the structural elements by the fires.
- 4. The response of the damaged and heated building structure, and the progression of structural component failures leading to the initiation of the collapse of the towers.

For such complex structures and complex thermal and structural processes, each of these steps stretched the state of the technology and tested the limits of software tools and computer hardware. For example, the investigators advanced the state-of-the-art in the measurement of construction material properties and in structural finite element modeling. New modeling capability was developed for the mapping of firegenerated environmental temperatures onto the building structural components.

The output of the four-step simulations was subject to uncertainties in the as-built condition of the towers, the interior layout and furnishings, the aircraft impact, the internal damage to the towers (especially the thermal insulation for fire protection of the structural steel, which is colloquially referred to as *fireproofing*), the redistribution of the combustibles, and the response of the building structural components to the heat from the fires. To increase confidence in the simulation results, NIST used the visual evidence, eyewitness accounts from inside and outside the buildings, laboratory tests involving large fires and the heating of structural components, and formal statistical methods to identify influential parameters and quantify the variability in analysis results.

- Combination of the knowledge gained into probable collapse sequences for each tower,<sup>2</sup> the identification of factors that contributed to the collapse, and a list of factors that could have improved building performance or otherwise mitigated the loss of life.
- Compilation of a list of findings that respond to the first three objectives and a list of recommendations that responds to the fourth objective.

## **E.3 SUMMARY OF FINDINGS**

Objective 1: Determine why and how WTC 1 and WTC 2 collapsed following the initial impacts of the aircraft.

• The two aircraft hit the towers at high speed and did considerable damage to principal structural components (core columns, floors, and perimeter columns) that were directly impacted by the aircraft or associated debris. However, the towers withstood the impacts and would have remained standing were it not for the dislodged insulation (fireproofing) and the subsequent multi-floor fires. The robustness of the perimeter frame-tube system and the large size of the buildings helped the towers withstand the impact. The structural system redistributed loads from places of aircraft impact, avoiding larger scale damage upon impact. The hat truss, a feature atop each tower which was intended to support a television antenna, prevented earlier collapse of the building core. In each tower, a different combination of impact damage and heat-weakened structural components contributed to the abrupt structural collapse.

The focus of the Investigation was on the sequence of events from the instant of aircraft impact to the initiation of collapse for each tower. For brevity in this report, this sequence is referred to as the "probable collapse sequence," although it includes little analysis of the structural behavior of the tower after the conditions for collapse initiation were reached and collapse became inevitable.

- In WTC 1, the fires weakened the core columns and caused the floors on the south side of the building to sag. The floors pulled the heated south perimeter columns inward, reducing their capacity to support the building above. Their neighboring columns quickly became overloaded as columns on the south wall buckled. The top section of the building tilted to the south and began its descent. The time from aircraft impact to collapse initiation was largely determined by how long it took for the fires to weaken the building core and to reach the south side of the building and weaken the perimeter columns and floors.
- In WTC 2, the core was damaged severely at the southeast corner and was restrained by the east and south walls via the hat truss and the floors. The steady burning fires on the east side of the building caused the floors there to sag. The floors pulled the heated east perimeter columns inward, reducing their capacity to support the building above. Their neighboring columns quickly became overloaded as columns on the east wall buckled. The top section of the building tilted to the east and to the south and began its descent. The time from aircraft impact to collapse initiation was largely determined by the time for the fires to weaken the perimeter columns and floor assemblies on the east and the south sides of the building. WTC 2 collapsed more quickly than WTC 1 because there was more aircraft damage to the building core, including one of the heavily loaded corner columns, and there were early and persistent fires on the east side of the building, where the aircraft had extensively dislodged insulation from the structural steel.
- The WTC towers likely would not have collapsed under the combined effects of aircraft
  impact damage and the extensive, multi-floor fires that were encountered on September 11,
  2001, if the thermal insulation had not been widely dislodged or had been only minimally
  dislodged by aircraft impact.
- In the absence of structural and insulation damage, a conventional fire substantially similar to or less intense than the fires encountered on September 11, 2001, likely would not have led to the collapse of a WTC tower.
- NIST found no corroborating evidence for alternative hypotheses suggesting that the WTC towers were brought down by controlled demolition using explosives planted prior to September 11, 2001. NIST also did not find any evidence that missiles were fired at or hit the towers. Instead, photographs and videos from several angles clearly showed that the collapse initiated at the fire and impact floors and that the collapse progressed from the initiating floors downward, until the dust clouds obscured the view.

Objective 2: Determine why the injuries and fatalities were so high or low depending on location, including all technical aspects of fire protection, occupant behavior, evacuation, and emergency response.

• Approximately 87 percent of the estimated 17,400 occupants of the towers, and 99 percent of those located below the impact floors, evacuated successfully. In WTC 1, where the aircraft destroyed all escape routes, 1,355 people were trapped in the upper floors when the building collapsed. One hundred seven people who were below the impact floors did not survive. Since the flow of people from the building had slowed considerably 20 min before the tower collapsed, the stairwell capacity was adequate to evacuate the occupants on that morning.

- In WTC 2, before the second aircraft strike, about 3,000 people got low enough in the building to escape by a combination of self-evacuation and use of elevators. The aircraft destroyed the operation of the elevators and the use of two of the three stairways. Eighteen people from above the impact zone found a passage through the damaged third stairway (Stairwell A) and escaped. The other 619 people in or above the impact zone perished. Eleven people who were below the impact floors did not survive. As in WTC 1, shortly before collapse, the flow of people from the building had slowed considerably, indicating that the stairwell capacity was adequate that morning.
- About 6 percent of the survivors described themselves as mobility impaired, with recent injury and chronic illness being the most common causes; few, however, required a wheelchair. Among the 118 decedents below the aircraft impact floors, investigators identified seven who were mobility impaired, but were unable to determine the mobility capability of the remaining 111.
- A principal factor limiting the loss of life was that the buildings were one-third to one-half occupied at the time of the attacks. NIST estimated that if the towers had been fully occupied with 20,000 occupants each, it would have taken just over 3 hours to evacuate the buildings and about 14,000 people might have perished because the stairwell capacity would not have been sufficient to evacuate that many people in the available time. Egress capacity required by current building codes is determined by single floor calculations that are independent of building height and does not consider the time for full building evacuation.
- Due to the presence of assembly use spaces at the top of each tower (Windows on the World restaurant complex in WTC 1 and the Top of the World observation deck in WTC 2) that were designed to accommodate over 1,000 occupants per floor, the New York City Building Code would have required a minimum of four independent means of egress (stairs), one more than the three that were available in the buildings. Given the low occupancy level on September 11, 2001, NIST found that the issue of egress capacity from these places of assembly, or from elsewhere in the buildings, was not a significant factor on that day. It is conceivable that such a fourth stairwell, depending on its location and the effects of aircraft impact on its functional integrity, could have remained passable, allowing evacuation by an unknown number of additional occupants from above the floors of impact. If the buildings had been filled to their capacity with 20,000 occupants, the required fourth stairway would likely have mitigated the insufficient egress capacity for conducting a full building evacuation within the available time.
- Evacuation was assisted by participation in fire drills within the previous year by two-thirds of survivors and perhaps hindered by a Local Law that prevented employers from requiring occupants to practice using the stairways. The stairways were not easily navigated in some locations due to their design, which included "transfer hallways," where evacuees had to traverse from one stairway to another location where the stairs continued. Additionally, many occupants were unprepared for the physical challenge of full building evacuation.
- The functional integrity and survivability of the stairwells was affected by the separation of the stairwells and the structural integrity of stairwell enclosures. In the impact region of WTC 1, the stairwell separation was the smallest over the building height—clustered well

within the building core—and all stairwells were destroyed by the aircraft impact. By contrast, the separation of stairwells in the impact region of WTC 2 was the largest over the building height—located along different boundaries of the building core—and one of three stairwells remained marginally passable after the aircraft impact. The shaft enclosures were fire rated but were not required to have structural integrity under typical accidental loads: there were numerous reports of stairwells obstructed by fallen debris from damaged enclosures.

- The active fire safety systems (sprinklers, smoke purge, fire alarms, and emergency occupant communications) were designed to meet or exceed current practice. However, with the exception of the evacuation announcements, they played no role in the safety of life on September 11 because the water supplies to the sprinklers were damaged by the aircraft impact. The smoke purge systems operated under the direction of the fire department after fires were not turned on, but they also would have been ineffective due to aircraft damage. The violence of the aircraft impact served as its own alarm. In WTC 2, contradictory public address announcements contributed to occupant confusion and some delay in occupants beginning to evacuate.
- For the approximately 1,000 emergency responders on the scene, this was the largest disaster they had even seen. Despite attempts by the responding agencies to work together and perform their own tasks, the extent of the incident was well beyond their capabilities. Communications were erratic due to the high number of calls and the inadequate performance of some of the gear. Even so, there was no way to digest, test for accuracy, and disseminate the vast amount of information being received. Their jobs were complicated by the loss of command centers in WTC 7 and then in the towers after WTC 2 collapsed. With nearly all elevator service disrupted and progress up the stairs taking about 2 min per floor, it would have taken hours for the responders to reach their destinations, assist survivors, and escape had the towers not collapsed.

# Objective 3: Determine what procedures and practices were used in the design, construction, operation, and maintenance of WTC 1 and WTC 2.

- Because of The Port Authority's establishment under a clause of the United States Constitution, its buildings were not subject to any state or local building regulations. The buildings were unlike any others previously built, both in their height and in their innovative structural features. Nevertheless, the actual design and approval process produced two buildings that generally were consistent with nearly all of the provisions of the New York City Building Code and other building codes of that time that were reviewed by NIST. The loads for which the buildings were designed exceeded the New York City code requirements. The quality of the structural steels was consistent with the building specifications. The departures from the building codes and standards identified by NIST did not have a significant effect on the outcome of September 11.
- For the floor systems, the fire rating and insulation thickness used on the floor trusses, which
  together with the concrete slab served as the main source of support for the floors, were of
  concern from the time of initial construction. NIST found no technical basis or test data on
  which the thermal protection of the steel was based. On September 11, 2001, the minimum

specified thickness of the insulation was adequate to delay heating of the trusses; the amount of insulation dislodged by the aircraft impact, however, was sufficient to cause the structural steel to be heated to critical levels.

Filed 10/08/2007

- Based on four standard fire resistance tests that were conducted under a range of insulation and test conditions, NIST found the fire rating of the floor system to vary between 3/4 hour and 2 hours; in all cases, the floors continued to support the full design load without collapse for over 2 hours.
- The wind loads used for the WTC towers, which governed the structural design of the external columns and provided the baseline capacity of the structures to withstand abnormal events such as major fires or impact damage, significantly exceeded the requirements of the New York City Building Code and other building codes of the day that were reviewed by NIST. Two sets of wind load estimates for the towers obtained by independent commercial consultants in 2002, however, differed by as much as 40 percent. These estimates were based on wind tunnel tests conducted as part of insurance litigation unrelated to the Investigation.

#### **E.4** RECOMMENDATIONS

The tragic consequences of the September 11, 2001, attacks were directly attributable to the fact that terrorists flew large jet-fuel laden commercial airliners into the WTC towers. Buildings for use by the general population are not designed to withstand attacks of such severity; building regulations do not require building designs to consider aircraft impact. In our cities, there has been no experience with a disaster of such magnitude, nor has there been any in which the total collapse of a high-rise building occurred so rapidly and with little warning.

While there were unique aspects to the design of the WTC towers and the terrorist attacks of September 11, 2001, NIST has compiled a list of recommendations to improve the safety of tall buildings, occupants, and emergency responders based on its investigation of the procedures and practices that were used for the WTC towers; these procedures and practices are commonly used in the design, construction, operation, and maintenance of buildings under normal conditions. Public officials and building owners will need to determine appropriate performance requirements for those tall buildings, and selected other buildings, that are at higher risk due to their iconic status, critical function, or design.

The topics of the recommendations in eight groups are listed in Table E-1. The ordering does not reflect any priority.

The eight major groups of recommendations are:

- Increased Structural Integrity: The standards for estimating the load effects of potential hazards (e.g., progressive collapse, wind) and the design of structural systems to mitigate the effects of those hazards should be improved to enhance structural integrity.
- Enhanced Fire Endurance of Structures: The procedures and practices used to ensure the fire endurance of structures should be enhanced by improving the technical basis for construction classifications and fire resistance ratings, improving the technical basis for standard fire resistance testing methods, use of the "structural frame" approach to fire resistance ratings,

and developing in-service performance requirements and conformance criteria for sprayed fire-resistive material.

- New Methods for Fire Resistant Design of Structures: The procedures and practices used in the fire resistant design of structures should be enhanced by requiring an objective that uncontrolled fires result in burnout without local or global collapse. Performance-based methods are an alternative to prescriptive design methods. This effort should include the development and evaluation of new fire resistive coating materials and technologies and evaluation of the fire performance of conventional and high-performance structural materials.
- <u>Improved Active Fire Protection:</u> Active fire protection systems (i.e., sprinklers, standpipes/hoses, fire alarms, and smoke management systems) should be enhanced through improvements to design, performance, reliability, and redundancy of such systems.
- Improved Building Evacuation: Building evacuation should be improved to include system
  designs that facilitate safe and rapid egress, methods for ensuring clear and timely emergency
  communications to occupants, better occupant preparedness for evacuation during
  emergencies, and incorporation of appropriate egress technologies.
- Improved Emergency Response: Technologies and procedures for emergency response should be improved to enable better access to buildings, response operations, emergency communications, and command and control in large-scale emergencies.
- Improved Procedures and Practices: The procedures and practices used in the design, construction, maintenance, and operation of buildings should be improved to include encouraging code compliance by nongovernmental and quasi-governmental entities, adoption and application of egress and sprinkler requirements in codes for existing buildings, and retention and availability of building documents over the life of a building.
- Education and Training: The professional skills of building and fire safety professionals should be upgraded though a national education and training effort for fire protection engineers, structural engineers, architects, and building regulatory and fire service personnel.

The recommendations call for action by specific entities regarding standards, codes and regulations, their adoption and enforcement, professional practices, education, and training; and research and development. Only when each of the entities carries out its role will the implementation of a recommendation be effective.

The recommendations do not prescribe specific systems, materials, or technologies. Instead, NIST encourages competition among alternatives that can meet performance requirements. The recommendations also do not prescribe specific threshold levels; NIST believes that this responsibility properly falls within the purview of the public policy setting process, in which the standards and codes development process plays a key role.

NIST believes the recommendations are realistic and achievable within a reasonable period of time. Only a few of the recommendations call for new requirements in standards and codes. Most of the recommendations deal with improving an existing standard or code requirement, establishing a standard

for an existing practice without one, establishing the technical basis for an existing requirement, making a current requirement risk-consistent, adopting or enforcing a current requirement, or establishing a performance-based alternative to a current prescriptive requirement.

NIST strongly urges that immediate and serious consideration be given to these recommendations by the building and fire safety communities in order to achieve appropriate improvements in the way buildings are designed, constructed, maintained, and used and in evacuation and emergency response procedures—with the goal of making buildings, occupants, and first responders safer in future emergencies.

NIST also strongly urges building owners and public officials to (1) evaluate the safety implications of these recommendations to their existing inventory of buildings and (2) take the steps necessary to mitigate any unwarranted risks without waiting for changes to occur in codes, standards, and practices.

NIST further urges state and local agencies to rigorously enforce building codes and standards since such enforcement is critical to ensure the expected level of safety. Unless they are complied with, the best codes and standards cannot protect occupants, emergency responders, or buildings.

				_			_											
ŀ	on to	ome	Unrelated <sup>b</sup>		>	>	>	>	`	>		>		>				>
	Relation to 9/11	Outcome	Related <sup>a</sup>	<b> </b>							>		1		>	>	>	>
	;	鴚	Selected Other High-Risk Buildings	,	>					>	>	>	>	`	`		>	>
		App	All Tall Buildings	>	>	>	>	>	>	>	>	>	>	>	>	>	>	>
			Education & Training	>						>	>	^			=			
			R&D/Further Study	>	>	>	^	>	>		>	^	>	>	>	>	>	>
and h	Ç		Adoption & Enforcement	<u> </u>					>	>	>							
Table E-1. Topics of NIST recommendations for improved public safety in tall and high-risk buildings.		립	Standards, Codes, Regulations	>	>	`	>	>	>	,	,	>	>		>	>	`	>
			Practices	>	>	^	/		>		>	>	>	>	>	-		>
			Recommendation Topic	Prevention of progressive collapse and failure analysis of complex systems	Estimation of wind loads and their effects on tall buildings	Allowable tall buildings sway	Fire resistance rating requirements and construction classification	Fire resistance testing of building components and extrapolation of test data to qualify untested building components	In-service performance requirements and inspection procedures for sprayed fire-resistive material (SFRM or spray-on fireproofing)	"Structural frame" approach (structural members connected to columns carry the higher fire resistance rating of the columns)	Burnout without partial or global (total) structural collapse in uncontrolled building fires	Performance-based design and retrofit of structures to resist fires	New fire-resistive coating materials, systems, and technologies	Evaluation of high performance structural materials under conditions expected in building fires	Performance and redundancy of active fire protection systems to accommodate the greater risks associated with tall buildings	Advanced fire alarm and communication systems that provide continuous, reliable, and accurate information on life safety conditions to manage the evacuation process.	Advanced fire/emergency control panels with more reliable information from the active fire protection systems to provide tactical decision aids	Improved transmission to emergency responders, and off-site or black box storage, of information from building monitoring systems
Ta			Recommendation Group	Increased	Structural	Integrity	Enhanced Fire	Endurance of Structures			New Methods for Fire Resistant	Design of	Structures		Improved Active Fire Protection			

Filed 10/08/2007

· ·	,	,													Exec	4,,,,
on to [1] ome	Unrelated <sup>b</sup>	>	>								>	>				>
Ple Community Application	Related	>	>	>	>	>	>	>	>	>			>	>	>	
lication	Selected Other High-Risk Buildings		>		>	>			>		`	^	>	`	>	>
App	All Tall Buildings	>	>	>	>	>	>	>	>	>	<b>\</b>	>	>	>	>	>
y	Education & Training	>	>		>			>	>	>				>	>	>
munit	R&D/Further Study	>	>			>	>	>	>	^				i		
le Com	Adoption & Enforcement							>	>	>	`	>	>			
Responsib	Standards, Codes, Regulations	>	>	>	>	>	,	>	`	>	,		>	>	>	
	Practices	>	>	>	>	>	1	1	<u> </u>	>	>	>	<u> </u>	>	>	>
	Recommendation Topic	Public education and training campaigns to improve building occupants' preparedness for evacuation	Tall building design for timely full building emergency evacuation of occupants	Design of occupant-friendly evacuation paths that maintain functionality in foreseeable emergencies	Planning for communication of accurate emergency information to building occupants	Evaluation of alternative evacuation technologies, to allow all occupants equal opportunity for evacuation and to facilitate emergency response access	Fire-protected and structurally hardened elevators	Effective emergency communications systems for large-scale emergencies	Enhanced gathering, processing, and delivering of critical information to emergency responders	Effective and uninterrupted operation of the command and control system for large-scale building emergencies	Provision of code-equivalent level of safety and certification of as-designed and as-built safety by nongovernmental and quasi-governmental entities	Egress and sprinkler requirements for existing buildings	Retention and off-site storage of design, construction, maintenance, and modification documents over the entire life of the building; and availability of relevant building information for use by responders in emergencies	Design professional responsibility for innovative or unusual structural and fire safety systems	Professional cross training of fire protection engineers, architects, structural engineers, and building regulatory and fire service personnel.	Training in computational fire dynamics and thermostructural analysis
	Recommendation Group	Improved Building	Evacuation				Improved	Emergency	Kesponse		Improved Procedures and	Practices			Education and Training	

a. If in place, could have changed the outcome on September 11, 2001.
 b. Would not have changed the outcome, yet is an important building and fire safety issue that was identified during the course of the Investigation.

This page intentionally left blank.